

THE RESULT OF MONITORING IN FRANCE



The concept



- 2 instrumented walls
- 2 instrumented building

8 sensors by wall

an internet connection to recover data






House in Morancé (69) near Lyon




Architect : Stéphane Peignier Straw compagny : Batinature









House in Morancé (69) near Lyon







16 sensors (relative humidity and temperature)







A nursery in Muel (Bretagne)



Architect : Stéphane Peignier Straw compagny : Batinature






A nursery in Muel (Bretagne)















A nursery in Muel (Bretagne)










Results data contact Morancé project BEHRENS measuring Allege 15 bain 100 KRAUSE point Allege 5 cuisine Linteau 15 90 Linteau 5 80 for multiple choice 70 time interval 60 t->temp / rel. humidity 🔍 type 50 ✓ usercolors line 40 resolution standard v 30 actions S sqi 20 legend Morancé bain.Allege_15@all 10 Morancé .bain.Allege_5@all -0 Morancé .bain.Linteau_15@all -10 Morancé .bain.Linteau_5@all -20 2013 2012






Analysis - Software








Analysis - Concept



Processing:


- Plot paires (T; RH)
- Point-to-point comparison between points and curves
- Comparison between the episode duration and the limit time of curves







Analysis - Outputs



Potential mould growth

Start date	Duration



